

Products affected:

BP 103	SFH 462
BPW 21	SFH 464
BPX 38	SFH 480
BPX 43	SFH 4811
BPX 61	SFH 4813
BPX 65	SFH 482
BPY 62	SFH 483
LD 242	SFH 4850
SFH 216	SFH 4860
SFH 221	SFH 4863
SFH 3831	SFH 4880
SFH 3832	SFH 4881
SFH 3833	SFH 4883
SFH 3834	SFH 530
SFH 400	SFH 5840
SFH 401	

Remark:

==> Except **SFH 530**, for all Metal Can products the die attach glue has to be replaced (additionally to the transfer)

==> Product names with green background: Metal Can products where the wire material changes (additionally to the transfer).